# Oil Field Environmental Incident Summary

Date/Time of Notice: 04/04/2015 17:41 Incident: 20150404174121 Responsible Party: PETRO-HUNT, L.L.C. Well Operator: PETRO-HUNT, L.L.C. Well Name: MOODY 159-94-15A-22-1H Field Name: NORTH TIOGA Well File #: 23800 Date Incident: 4/4/2015 Time Incident: 14:00 Facility ID Number: **BURKE** Twp: 159 **Rna**: 94 **Sec:** 15 **Qtr:** County: Location Description: Submitted By: Derek Enderud Received By: Contact Person: Derek Enderud **PO BOX 935** BISMARCK, ND 58502 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Valve/Piping Connection Leak Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units Followup **Units** 2 2 Oil Barrels Barrels **Brine** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: none Areal Extent:

## Potential Environmental Impacts:

none, stayed on location.

#### Action Taken or Planned:

Temporarily replaced gauge with plug, will replace gauge.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

### **Updates**

Date: 4/5/2015 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.